Work Orde		913									Page 1
Item ID: Revision ID:	D4012-1			Accept				se se			
	Cushion 20/04/2010 29/04/2010	Start Qty: 40. Req'd Qty: 40.		18 18 18 18 18 18 18 18	Cust Iten Custome				St		
Approvals:	Process Pla	n: <i>[[]</i>	Date://	-1/-2 ()Tooling: SPC (Y/N):		Date:		R			
Sequence ID/ Work Center II)	Operation Description		Set Up/ Run Hours	Draw Numbe	Draw r Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr									
D4012	A										
100 Doosan Doosan Lathe		FOLIC		0.00 0.00 & dwg D	10/07/01			40			· •
			urr as required								

0.00

0.00

QC2- Inspect parts off machine FAI/FAIB

Memo

Quality Control

Dart Aerospace Ltd	d
--------------------	---

Part No:PAR #:Fault Category:NCR: Yes No DQA:Date: Resolution:Disposition:QA: N/C Closed:Date: NCR: WORK ORDER NON-CONFORMANCE (NCR) DATE STEP Description of NCCorrective Action Section B	W/O:			W	ORK ORDER CHANGI	ES					
Resolution:	DATE	STEP	PRO	CEDURE CHA	ANGE	Ву	Date	Qty	Chief Eng /	Approval QC Inspector	
Resolution:											
Resolution:											
Resolution:											
Resolution:											
Resolution:											
NCR: WORK ORDER NON-CONFORMANCE (NCR) DATE STEP Description of NC Section A Section B Section B Section C Chief Eng OC Inspector C C Chief Eng OC Inspector C C Chief Eng OC Inspector C C C C C C C C C C C C C C C C C C C	Part No:	•	PAR #:	Fault Cate	egory:	NCR: Yes	s No DQA		Date: _		
DATE STEP Description of NC Section A Section B Section B Section B Section C Chief Eng OC Inspector C Section C Section C Chief Eng OC Inspector C Chief Eng OC Inspector C C Section C Chief Eng OC Inspector C C C C C C C C C C C C C C C C C C C		R	esolution:	lution: QA: N/C Closed:				Date:`			
DATE STEP Description of NC Initial Action Description Sign & Verification Approval Approval Approval Section C Chief Eng. OC Inspector	NCR:		\	WORK ORD	ER NON-CONFORMA	NCE (NC	R)				
Section A Initial Action Description Sign & Section C Chief Eng QC Inspector	DATE	STEP	Description of NC				Verifica	ion	Approval	Approval	
		0.2.	Section A					r C		QC Inspector	
					PR-199.						
			·						:		

Work Order ID 57913



Page 2

April 20, 2010 10:02:37 AM

Required Date: 29/04/2010

Item ID:

D4012-1

Accept

Setup Start



Revision ID:

Item Name:

Cushion

QC:

Start Date:

20/04/2010

Start Qty: 40.00

Req'd Qty: 40.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____

Date:_____

Date:

Tooling:

SPC (Y/N):

Date:

Date:

Draw

Rev.

Run S

Start

Stop



Stop

Sequence ID/ Work Center ID

120

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

Memo

Set Up/ Run Hours

0.00

Number 16/07/24

Draw

Plan Code

Accept Qty

Reject Qty Reject Insp. Number Stamp

40

130

Packaging

Packaging

Identify as per dwg & Stock Location:

0.00

10.7.0

\$ 40

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

CZ1017/05

1009:06

Dart /	Aeros _i	pace	Ltd
--------	--------------------	------	-----

W/O:			W	ORK ORDER CHANG	ES						
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	

Part No):	PAR #:	Fault Cate	gory:	_ NCF	R: Yes I	No DQA:		Date:	Date:	
	Resolution: Disposition: QA: N/C Closed: D								Date:		
NCR:		WORK ORDER NON-COI				(NCR					
DATE	STEP	Description of NC		Corrective Action Section	on B		Verifica	tion	Approval	Approval	
DAIL	JIL.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector	
·									·		
ļ											
	1.					·					
								1			

April 20, 2010 10:02:41 AM

Work Order ID: 57913

Parent Item: D4012-1

Parent Item Name: Cushion

IPP RevA: New issue 09.10.28 DD verified by:JLM **Comments:**

Replacement Mfg/

revA as per dwg 09.11.18 DD verified by:JLM

Bin

No

Primary

Item Location

Item ID Purch Purchased

MUHMWT3.500X3.000

UHMW Tubing 3.5" x 3"

Component Item ID/

Item Name

Route

Seq ID

100

IPP RevB:

Last

Location

Start Date: 20/04/2010

Required Date: 29/04/2010

Start Qty: 40.00

Required Qty: 40.00

Date

Remaining Qty Qty To Pick Issued

5.2758

Issued

Status

M 114658

Unit of

Measure

Qty on


Hand

0.0000

5.0

Dart	Aer	osp	ace	Ltd

	•										
W/O:			WO	RK ORDER CHAN	GES						
DATE	STEP	PR	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No		PAR #:								 	
	Res	solution:							Date:		
NCR:			WORK ORDE	ER NON-CONFORM	IANCE	(NCR)	l			
DATE	STEP	Description of NC			ction B	Ciara 9	Verifica	ion	Approval	Approval	
	-	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	ıC	Chief Eng	QC Inspector	
			·								
		·									
										-	
					1			ł		ľ	



Dart Ae	rospace	Ltd								₽ .
W/O:		WORK ORDER CHANGES							·	
DATE	STEP	PRO	CEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect
										- 15 T
Part No):	PAR #:	Fault Categ	ory:	NC	R: Yes	No DQA		Date: _	
1	R	esolution:	Disposition	:	QA	: N/C Cld	sed:		Date: _	
NCR:		V	VORK ORDE	R NON-CONFO	PRMANCE	(NCR)			-
DATE	STEP	Description of NC		Corrective Action	Section B		Verifica	tión	Approval	Approva
DATE	SIEP	Section A	Initial Chief Eng	Action Descrip Chief Eng	otion	Sign & Date	Section		Chief Eng	QC Inspect
	,									
						·				
										· ·
		•								

	57//
DART AEROSPACE LTD	Work Order:
DART AEROSPACE LID	
	Part Number: N4012-1
Description: Cushion	
	Page 1 of 1
Inspection Dwg: NHOIA Rev: A	

spection Dwg	:NHOIA Rev: A	1				Pag	e 1 of 1
		ARTICLE IN	SPECTIO	N CHE	CKLIST		
	X			Proto			
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of		ments
172	T - 30	1-25	1 55				
1.40	- .030	1/10					
140	±.030 ±.5°	140					
1.25 1.25	+ -030	1.250					
1.050	+ 010	1.049					
.031	1 .010	-032					
10	+030	100					
094	1015.	.089	/				
03/24/50	+.010 ± .50	-025 X45°	/				
			<u> </u>	ļ			
				1			
_				<u> </u>			
			 	-			
				+			
				-		· ·	
				 			
			 	1,			
			 				
	<u></u>	1					N1/A
Measured by:		Audited by:	151		Prototype	Approval:	N/A N/A
Date:	10/07/01	Date:	10/07	101		Date:	
Rev Date	Change					Revised by	Approve
A	New Issue				1	KJ/JLM	